

**Child Access Routing Plan
2013-2014
Majestic Elementary School**

School Traffic Safety Committee Members

Principal:	Dave Wallace
School Safety Facilitator:	Danielle Short
PTA Co-Presidents:	Irene Wideman; Amy Simonsen
School Custodian:	Alan Faulkner
School Resource Officer:	Dennis Moore, Harrisville Police Department
Chairman, Community Council:	Robert Bischoff

1. *Written School Plan*

1.1 **Location:** Majestic Elementary School
425 West 2550 North
Harrisville, Utah 84414

1.2 **Existing Traffic Controls:**

- a. 4-Way Stop, 2425 North 450 West (with crosswalks on 3-sides)
- b. 3-Way Stop, 2425 North 350 West
- c. 2-Way Stop, 2300 North 600 West
- d. 2-Way Stop, 2150 North 600 West
- e. 2-Way Stop, 2550 North 550 West
- f. Single Stop, 2550 North 350 West (Hillsborough)
- g. Single Stop, 2550 North 450 West
- h. Single Stop, 2550 North 575 West
- i. Single Stop, 2550 North 600 West
- j. Single Stop, 2350 North 350 West
- k. Single Stops, 2300 North 350 West, 375 West, 400 West, 450 West, 500 West, 550 West, 650 West, 700 West, 750 West.
- l. Single Stop, 2150 North 750 West
- m. Single Stop, 2125 North 500 West
- n. Yield, 2100 North 150 East
- o. Single Stop, 2050 North 150 East
- p. 2-way Stop, 2000 N 150 East
- q. Single Stop, 2000 North 425 West, 550 West, 600 West, 400 West
- r. Yield 1900 North 300 East
- s. Single Stop, 1875 North 200 West
- t. Yield 1875 North 150 West
- u. 2-way Stop/Yield 1875 North 150 East

1.3 **Sidewalks needed:**

- a. approximately 180 yards of sidewalk from 400 West to 290 West along 2550 North
- b. approximately 300 yards of sidewalk from 125 West to 235 East along 2550 North

1.4 **Established Narrow School Routes:** 2550 North from 166 West to Hwy. 89

1.5 **Future Growth area:**

High density housing development on the north side of 2550 North and 250 West

Sub-division development south of Majestic Elementary between the school and 2000 North

Sub-division development north of Majestic Elementary north of 2700 North and west of 1000 West

Proposed sub-division south of 1900 North and East of 150 East

1.6 **Present Access Routes:** See Maps A & B

Student populations East of Majestic Elementary (See Map A)

South of North Shore Swimming Pool (Browns Farm, Sunbrook, Black Hawk areas):

Students living in this area have sidewalk access to the school by taking the most direct route to 200 East. Students should be cautious of the traffic associated with pick-up/drop-off activity at the Montessori school located at 2505 North 200 East. Students may use the school crossing at 200 East. Students would then proceed along the available sidewalks on the south side of 2550 North. Students should be cautious of two areas that lack sidewalk and have minimum shoulder area at approximately 235 East ← → 125 West and 290 West ← → 400 West because of the traffic speeds and volume associated with 2550 North.

Colonial Springs Condos (2550 North Charleston) (See Map A)

Students would then proceed along the available sidewalks on the south side of 2550 North. Students should be cautious of two areas that lack sidewalk and have minimum shoulder area at approximately 235 East ← → 125 West and 290 West ← → 400 West because of the traffic speeds and volume associated with 2550 North.

Student populations South of Majestic Elementary (See Map B)

Students living as far south as 1900 North may access the school by using sidewalks that travel along 150 East to 2150 North or at 200 West to 2150 North; 225 West to 2300 North, to 2425 North. Students should be cautious crossing 2000 North at 150 East or 200 West. Students will access the school property at two entry points located in the south-east and south-west corners of the school property. A paved walking track and bike racks are available on school property.

Student populations West of Majestic Elementary (See Map B)

Students living along 750 West are encouraged to use 2300 North to 600 West to 2425 North and access the school property at two entry points located in the south-east and south-west corners of the school property. A paved walking track and bike racks are available on school property.

Student populations North of Majestic Elementary (including Cove Apartments) (See Map A)

Most students who live North of 2700 North are bussed. Students who live in the Cove Apartment complex are required to cross 2550 North at 350 West. Please be cautious of the traffic associated with 2550 North.

1.7 Bicycle Routes

Student populations East of Majestic Elementary are discouraged from riding their bikes to school because of the safety concerns associated with 2550 North

Student populations to the South and West of Majestic Elementary should use the same routes as the walkers. Bicycle safety practices should be used. Bicycle racks are available on school campus. Bicycle riders are expected to walk their bikes while on school campus and at all crossings.

The majority of student populations to the North of Majestic Elementary is bussed and should avoid riding bicycles to school because of the traffic concerns associated with 2700 North and 2550 North. Those students who live immediately across the street of 2550 North are also discouraged from riding their bikes because they would be asked to walk them across 2550 North and on school campus, thus minimizing the distance of actually riding the bike.

1.8 Bus loading and unloading areas: See Map C

Private vehicles should avoid the Bus-lane section of the large parking lot when busses are present. Students should always be accompanied by an adult when walking through the parking lot. All patrons should be cautious when walking through the parking lot when busses are present.

1.9 Vehicle loading and unloading areas: See Map C

Students are being dropped off on school campus should not be dropped off on 2550 North. It is requested that they be dropped off in the “Kindergarten” drop-off/pick-up area when busses are present and on the curb of the large parking lot when busses are not present. Students should always be accompanied by an adult when walking through the parking lot. Students may also be dropped off at the curb behind the school along 2425 North.

1.10 Hazards

2550 North: The lack of sidewalks, ditch (with water), open well, lack of shoulder, speeds and volume of traffic make 2550 North an area of concern.

2000 North/150 East: The traffic along 2000 North is a concern.

2. Maps
 - 2.1_ Map A: East population access route
 - 2.2_ Map B: South population access route
 - 2.3_ Map C: Loading/Unloading areas for parent vehicles and busses
3. Recommendations
 - 3.1_ 2550 North: Improved road expansion, sidewalks, or an alternative walking path that would be completely separate from 2550 North.
 - 3.2_ Speed reduction, particularly when students are present, along 2550 North.
 - 3.3_ Painted crossings at 2550 North and Hillsborough; both east/ west and north/south.
 - 3.4_ Painted crossings at 2000 North and 150 East and 200 West
 - 3.5_ Additional signage, lighting, cross-walks, and crossing guards at the above locations (3.3 and 3.4)

Note: In May, 2013 and September, 2013, meetings were held with city officials from the three communities, Weber School District leaders, and local school personnel (PTA/Community Council) in order to address the safety concerns. These officials have been very receptive to our concerns. Additional signage has been added to 2550 North as a response to these discussions. We recognize the planning and budgetary challenges that face these entities. We believe that the communities are concerned about the safety concerns facing Majestic Elementary and will do all they reasonably can to ensure the safety of our students.

The following people approved of the Child Access Routing Plan given the current existing conditions:

- _____ **Dave Wallace, Principal**

- _____ **Danielle Short, School Safety Facilitator**

- _____ **Irene Wideman, PTA Co-President**

- _____ **Amy Simonsen, PTA Co-President**

- _____ **Alan Faulkner, School Custodian**

- _____ **Dennis Moore, Harrisville Police**

- _____ **Robert Bischoff, Community Council**